



### Note on Engineering Details

**No:** DWM-Schl-extern-004

**Title:** Erratum in Offshore Guideline

**Ref.:** Germanischer Lloyd "Guideline for the Certification of Offshore Wind Turbines",  
Edition 2005  
Section 8.10.5(9)

**Contact:** Reinhard Schleesselmann, email: [reinhard.schleesselmann@gl-group.com](mailto:reinhard.schleesselmann@gl-group.com),  
phone: +49 40 31106 116

**Key Words:** Offshore Wind Turbine, Grid Device, Cable, Erratum, Offshore Guideline

In our "Guideline for the Certification of Offshore Wind Turbines", Edition 2005 the following erratum was detected in section 8.10.5(9):

Text as printed:

(9) Section 8.5.5.1 shall be observed where applicable.

Correct text as to be applied:

(9) Section 8.5.5 shall be observed where applicable.

Hamburg, 29.05.2006

Christian Nath  
*Managing Director*

Mike Woebbeking  
*Head of Department*

Reinhard Schleesselmann  
*Author*

F:\DATA\WIND\ABTEILUNG\DWM\NOTIZEN\SCHL\ERNAS\DWM-SCHL-EXTERN-004.DOC

*Gerichtsstand und Erfüllungsort ist Hamburg. Es gelten die Allgemeinen Geschäftsbedingungen der Germanischen Lloyd WindEnergie GmbH in ihrer jeweils neuesten Fassung. Es gilt deutsches Recht.*

*Place of performance and jurisdiction is Hamburg. The latest edition of the General Terms and Conditions of Germanischer Lloyd WindEnergie GmbH is applicable. German law applies.*