

**Note on Engineering Details**

**No:** GL RC-M-MTr-extern-001

**Title:** Erratum in GL 2010

**Ref.:** "Guideline for the Certification of Wind Turbines", Edition 2010  
Section 7.7.4.(1)

**Contact:** Mirja Traulsen, e-mail: mirja.traulsen@gl-group.com, phone: +49 40 36149 - 7016

**Key Words:** GL 2010, Elastomer Bearings, Loads, Verifications

In our "Guideline for the Certification of Wind Turbines", Edition 2010 the following erratum was detected in section 7.7.4(1):

Text as printed:

(1) It shall be shown that the elastomer bearings provide adequate safety against the extreme and -

Correct text as to be applied:

(1) It shall be shown that the elastomer bearings provide adequate safety against the extreme and fatigue loads.

Hamburg, 14.12.2011

Peter Bollmann  
Wind Energy Committee, Chairman

Mike Woebbeking  
Wind Energy Committee, Secretary

Mike Woebbeking  
Head of Certification Body

Axel Dombrowski  
Head of Department

Axel Dombrowski  
Head of Group

Mirja Traulsen  
Author

Dr. Michael Hauschildt  
Head of Department

Andreas Kamleitner  
Head of Department

Andreas Anders  
Head of Department

Miguel Roeses Bueno  
Head of Department

Kimon Argyriadis  
Head of Department

Head of Department